#### Flood Control Project Maintenance Levee Inspections

## 2008 Channel Summary Report

## **Overall Unit and Item Ratings**

## **Placer County**

### **Truckee River**

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	Α
	Shoaling	М
	Encroachments	Α
	Rip Rap Revetments	Α
	Erosion	Α

Tuesday, April 07, 2009 13:20 Page 1 of 1

## **Unit Cover Sheet**

## 2008 Channel Inspection Results

# **Placer County**

Channel
Truckee River

Date of Inspection	7/22/2008
DWR Inspector	John Williamson
Channel Rating	Α

## **Inspection Report - Channel 2008**

# **Placer County**

Channel	Inspection Date	Inspector
Truckee River	07/22/2008	John Williamson

Rpt Line	Category	Item	Rating ** Location *	Comment	GF	PS	Photo	Issue
1	Structures & Concrete Lined Channels	Electric Gate Operators	Α	center of structure GPS point 39.16716 -120.14392		c		6
2	Structures & Concrete Lined Channels	Security Fencing	Α			ć		7
3	Rivers, Channels & Designated Floodways	Vegetation & Obstructions	Α	vegetation is not obstructing the flow of the river. There appeare to be no debris or other objects to effect flow. GPS point center of bike bridge 39.16508 -120. 15190		ć		1
4	Rivers, Channels & Designated Floodways	Shoaling	М			ć	) )	4
5	Rivers, Channels & Designated Floodways	Encroachments	А			ć		2
6	Rivers, Channels & Designated Floodways	Rip Rap Revetments	А	rip rap is in good condition and has no vegetation growing in it		ć		3
7	Rivers, Channels & Designated Floodways	Erosion	А			ć		5

\* Location LS : Land Side WS : Water Side CR : Crown \*\* Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected

C : Corrected

## **Inspection Report - Channel 2008**

# **Placer County**

Channel	Inspection Date	Inspector
Truckee River	07/22/2008	John Williamson

Report Line	1
Location	
Category	Structures & Concrete Lined Channels
Item	Electric Gate Operators

Outlet gate structure upstream from hwy 89 center of struture GPS 39.16716 -120.14392



Report Line	1
Location	
Category	Structures & Concrete Lined Channels
Item	Electric Gate Operators

Outlet structure



Report Line	3
Location	
	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from hwy 89 bridge



A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected

C : Corrected

## **Inspection Report - Channel 2008**

# **Placer County**

Channel	Inspection Date	Inspector
Truckee River	07/22/2008	John Williamson

Report Line	3
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream from bike bridge



Report Line	3
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from bike bridge



Report Line	3
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream from Tahoe City Lumber Yard



\* Location LS: Land Side WS: Water Side CR: Crown \*\* Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

Tuesday, April 07, 2009 13:21 Page 3 of 4

## **Inspection Report - Channel 2008**

# **Placer County**

Channel	Inspection Date	Inspector
Truckee River	07/22/2008	John Williamson

Report Line	3
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from Tahoe City Lumber Yard near downstream limit GPS east end of yard 39.16248 -120.15190



C : Corrected